

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER
TEX
15-SANT
30-

San Jose Gristmill
800 ft. East of Roosevelt Avenue
near San Jose Drive
San Antonio
Bexar County
Texas

HAER No. TX-2

Jet Lowe, HAER Photographer, July 1983

- TX-2-1 GENERAL VIEW OF GRISTMILL LOOKING NORTHWEST; WOODEN GUARDRAILS
ARE VISIBLE AROUND EQUALIZER VAT
- TX-2-2 GENERAL VIEW OF GRISTMILL LOOKING NORTHWEST
- TX-2-3 CLOSE-UP VIEW OF GRISTMILL LOOKING SOUTHWEST; TAILRACE VISIBLE
AT LOWER RIGHT
- TX-2-4 GENERAL VIEW OF TAILRACE LOOKING WEST
- TX-2-5 DETAIL VIEW OF EQUALIZER VAT WHERE WATER WAS HELD PRIOR TO
POWERING FLUTTER WHEEL
- TX-2-6 DETAIL VIEW OF FLUTTER WHEEL IN BASEMENT OF GRISTMILL. THE
RECTANGULAR ENCLOSED FLUME PROTRUDING FROM THE WALL AT
CENTER/LEFT CARRIED WATER FROM THE EQUALIZING VAT THAT
POWERED THE WHEEL
- TX-2-7 GENERAL VIEW OF MILLING ROOM LOOKING WEST
- TX-2-8 DETAIL INTERIOR VIEW OF GRINDSTONE AND ASSOCIATED EQUIPMENT
- TX-2-9 DETAIL VIEW OF DOOR AND HINGE